




V a l - C o
People. Products. Solutions.

www.valcompanies.com

Wire Requirement

INSTALATION	WIRES
Power Supply	Three Wires: Ground Neutral Phase
Temperature Sensor	Three Wires: (+) White 18/3 SHIELDED (s) Red (-) Black
Load Cell (Scales)	Three Wires: (+) Red 18/3 SHIELDED (s) White (-) Black
Water Counter or Feed Counter	Two Wires: (+) not connected (s) White 16/2 SHIELDED (-) Black



W R B

W R B

B W

Thermometer Leads: Brown to Black of Cable
: Green to Red of Cable
: White to White of Cable

Note: Wires may be European standard colors in which case: Red = Green, White = White, and Black = Brown.